1. ITEM 1 (FOIL) - NORTH BANK OF REACH 2 AT THE DOUBLE CULVERT.

2. VIEW OF THE AREA SURROUNDING ITEM 1.

3.   ITEM 2 (FOIL) – SOUTH BANK OF REACH 2 AT THE DOUBLE CULVERT.

4. VIEW OF AREA SURROUNDING ITEM 2.

5. ITEM 3 (UNKNOWN) – SOUTH BANK OF REACH 2, 30' DOWNSTREAM OF THE DOUBLE CULVERT.

6. VIEW OF AREA SURROUNDING ITEM 3.

7. ITEM 4 (SUSPECTED CAPACITOR PART) – SOUTH BANK OF REACH 2, 35'
DOWNSTREAM OF THE DOUBLE CULVERT.

8. VIEW OF THE AREA SURROUNDING ITEM 4.

9. ITEM 5 (METAL CAP. SUSPECTED TO BE ASSOCIATED WITH CAPACITOR EQUIPMENT.) – NORTH BANK OF REACH 2, APPROX. 100' UPSTREAM OF THE BRIDGE BETWEEN REACH 2 AND REACH 3.

10. VIEW OF AREA SURROUNDING ITEM 5.

11. ITEM 6 (PIECE OF METAL MARKED "RAMSEY") – SOUTH BANK OF REACH 2 AT THE OUTFALL PIPE NEAR THE BRIDGE BETWEEN REACH 2 & REACH 3.

12. VIEW OF AREA SURROUNDING ITEM 6.

13. ITEM 7 – SOUTH BANK OF REACH 2 AT THE FIRST OUTFALL PIPE. INDICATES AN AREA OF STRONG PETROLEUM-LIKE ODOR AND AN OIL-LIKE SHEEN ON THE WATER'S SURFACE.

14. VIEW OF THE SWALE FROM THE FIRST OUTFALL PIPE SURROUNDING ITEM 7.

15. ITEM 8 (SUSPECTED CAPACITOR PART) –REACH 2 IN THE TONGUE OF THE SINGLE CULVERT.

16. VIEW OF THE AREA SURROUNDING ITEM 8.

17. ITEM 10 (FOIL) – SOUTH BANK OF REACH 1 IMMEDIATELY UPSTREAM OF THE DOUBLE CULVERT.

18. VIEW OF AREA SURROUNDING ITEM 10 LOOKING UPSTREAM FROM THE SOUTH BANK.

19. ITEM 11 (FOIL) – SOUTH BANK OF REACH 1 IMMEDIATELY UPSTREAM OF THE DOUBLE CULVERT.

20. VIEW OF AREA SURROUNDING ITEM 11 LOOKING UPSTREAM FROM THE SOUTH BANK.

21. ITEM 12 (OIL-STAINED WOOD BLOCK) – SOUTH BANK OF REACH 1 IMMEDIATELY UPSTREAM OF THE DOUBLE CULVERT.

22. VIEW OF CHAIN LINK FENCE ADJACENT TO THE DOUBLE CULVERT.

23. ITEM 13 (FOIL) – SOUTH BANK OF REACH 1 IMMEDIATELY UPSTREAM OF THE DOUBLE CULVERT.

24. VIEW OF THE AREA SURROUNDING ITEM 13 LOOKING UPSTREAM FROM THE SOUTH BANK.

25. ITEM 14 (OIL-STAINED WOOD BLOCK) – SOUTH BANK OF REACH 1
UPSTREAM OF THE DOUBLE CULVERT

26. VIEW OF AREA SURROUNDING ITEM 14 LOOKING UPSTREAM